



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D5617-3
Job Sheet 203745



Part No: D5617-3

Job Qty: 11 pcs

Part Name: Clamp



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 11/27/19

Job Tracking No:

Due Date: 12/13/19

Created By: Eric Larocque

Type: SOLD

Description:

Note: D5617 REV.C IPP REV:A 19.07.30 NEW ISSUE DD VERF:DP

Ship Via:

Bill of Materials



Dart Aerospace
1270 Aberdeen St
Hawkesbury, ON K6A
CANADA
TEL.: 1 613 632-5200
Email: sales@dartae
www.dartaerospace.

Container No: S235306



Part No: D5617-3

Job No: 203745

Serial No/Batch: S235306

Revision: C

Director:

Job Routing									
Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Large Fab - Welded Assy-1	11 pcs		12/13/19	0.00	1.38		Large Fab - 1	ms
								Large Fab - 10	
								Large Fab - 2	
								Large Fab - 3	
								Large Fab - 4	
								Large Fab - 5	
								Large Fab - 6	
								Large Fab - 7	
								Large Fab - 8	
								Large Fab - 9	
								Large Fab - 11 (Various)	
								Large Fab - 12	
110	QC 5	11 pcs		12/13/19	0.00	0.00		QC 5 - 10	AL
								QC 5 - 12	
								QC 5 - 17	
								QC 5 - 18	
								QC 5 - 19	
								QC 5 - 22	
								QC 5 - 24	
								QC 5 - 3	
								QC 5 - 43	
								QC 5 - 49	
								QC 5 - 51	
								QC 5 - 58	
								QC 5 - 68	
								QC 5 - 9	
								QC 5 - 50	
								QC 5 - 30	
								QC 5 - 40	
								QC 5 - 61	
								QC 5 - 81	
120	Packaging 3-1 - Stock - B4B	11 pcs		12/13/19	0.00	0.00		Packaging 3 - 1 - B4B	AL
								Packaging 3 - 2 - B4B	
								Packaging 3 - 3 - B4B	
								Packaging 3 - 4 - B4B	
								Packaging 3 - 5 - B4B	
130	QC 21 - SA	11 pcs		12/13/19	0.00	0.00		QC 21 - SA - 21	DAS 21 9-50 NOV 27 2019
								QC 21 - SA - 70	
								QC 21 - SA - 53	
Part Op 100 - 1- Install clamp to 3.15" extrusion 2-CUT PARTS TO DIMENSIONS SHOWN. REMOVE 1.80" MATERIAL FROM Descriptions: CLAMP BAND. 110 - QC5- Inspect part completeness to step on W/O 120 - Identify as per dwg & Stock Location: _____ 130 - QC21- Final Inspection - Work Order Release									
Job BOM									
Part / Item	Component Name	Quantity	Operation	Container					
D5616-3	Supra Heavy Duty Hose Clamp Stainless Steel, W4 79-85	11 pcs (1 ea)	100-Large Fab - Welded Assy-1	S209603					
Job Allocations									
Operation	Component Part	Required	Inventory	Allocated					
100-Large Fab - Welded Assy-1	D5616-3	11	55	0					

Part Specifications

Specifications could not be found.

Plex 11/27/19 7:47 AM dart.larocque.eric